



# LEDGO INC. DIGITAL 42 SERIES LAMINATOR FUSE DIAGRAM




## FUSE REPLACEMENT LEGEND:

- A: 3AG .5 AMP FAST ACTING FUSE
- B: 3AG 1.5 AMP FAST ACTING FUSE
- C: 3AG 12 AMP FAST ACTING FUSE
- D: 3AG 8 AMP SLO-BLO FUSE



# LEDGO INC. DIGITAL 60 SERIES LAMINATOR FUSE DIAGRAM



## FUSE REPLACEMENT LEGEND:

- A: 3AG .5 AMP FAST ACTING FUSE
- B: 3AG 1.5 AMP FAST ACTING FUSE
- C: 3AG 20 AMP FAST ACTING FUSE
- D: 3AG 8 AMP SLO-BLO FUSE

